(Stack SDS 04)

V	[SIBI	LE EMISSIO	N NOTATION	ONS	/
			1		,

Inspector:

Ted Conston

Disce of Inspection:

Sight: 1st Shift or 2nd Shift Time:

Unit Visual

	Inspection <u>NORMAL</u>	
	or	
Visible Emission From Shaker	<u>ABNORMAL</u>	
	Nor	COST (CONTROL COST) COST (CONTROL COST (CONT
Visible Emission From Discharge Conveyor System	Nor	

Comments

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIBLE EMISSION NOTATIONS				
Inspector: George & San Ar	le			
Date of Inspection: 8/1//5	)			
Shift: 1st Shift or 2nd Shift	Time: 5:0	OAM		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

7101022 21111001011 11011101110				
Inspector:				
Date of Inspection:				4
Shift: 1st Shift or 2nd Shi	ft Time:			
Unit Visible Emission From Shaker	Visual Inspection NORMAL TOT ABNORMAL		Comments	
Visible Emission From Discharge Conveyor System	Norm			*

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

**************************************						
Inspector: Paul Carl	2					
Date of Inspection: 8-2-15						,
Shift: 1st Shift or 2nd Shif	t Time:	5:00 AM				
Unit	Vistral Inspection		Company of the Compan	omments		
	<u>NORMAL</u>					
	or <u>ABNÖRMAL</u>	en <b>jake</b> Postalaj singer			garage (1912) <b>19</b> 19	Marije iz same Marije iz selati
Visible Emission From Shaker	nov					
Visible Emission From Discharge Conveyor System	voc					
Conveyor System		L				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

#### **VISIBLE EMISSION NOTATIONS**

Visible Emission From Discharge

Conveyor System

Nor

Inspector: Gregore A. Sanch	er			
Date of Inspection: 8/3/15				
Shift: (1st Shift) or 2nd Shift	ft Time:	5:00 pm		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIB	LE	ΕN	AISS.	ION	NOT	ATIO	NS

			_		
Inspector:	onk				
Date of Inspection:	15				
Shift: 1st Shift or 2nd Shift	ft) Time:	5:00 Am			
Umit.	Visual Inspection NORMAL Or ABNORMAL			Comments	
Visible Emission From Shaker	nor				
Visible Emission From Discharge Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Crease A Sarch	, ec			
Date of Inspection: 8/4/15				
Shift: 1st Shift or 2nd Shif	t Time:	5.00 am		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

<b>VISIBI</b>	F	FM	ISSIC	ואר	TOIA	ΛTI	ONG
AIDIDI	г	LIVI	いっつい	ЛΝ	ועטוו	AII	CHAI

Inspector: Smello				
Date of Inspection: Aug 5 (	5			
Shift: 1st Shift or 2nd Shift	t Time:	SAM		
Unit	Visual Inspection <u>(NORIMAL</u> 407 ABNORIMAL		Comments	
Visible Emission From Shaker	nor	settetimenoners		
Visible Emission From Discharge Conveyor System	nor	and the same of th		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS				
Inspector: George A Song	her			
Date of Inspection: 8/5//5				
Shift: 1st Shift or 2nd Shift	Time:	5:00 per		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge	Nos			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VICIDIE	ER ALCCION	LALOTA	TIONIC
VISIBLE	<b>EMISSION</b>	INUIA	HONS

VISIBLE EIMISSICH NO MINIONS	·			
Inspector: Smello				
Date of Inspection:	\$			,
Shift: st Shift or 2nd Shi	ft Time:	5,00		
Unit	Visual Inspection NORMAL or ABNORMAL		Comments	
Visible Emission From Shaker	nor			
Visible Emission From Discharge Conveyor System	nove	gaarin		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS				
Inspector: Greene A Jan	rchec			
Date of Inspection:				
Shift: 1st Shift or 2nd Shift	Time:	5:00pm		
Unit	Visual		Comments	
	Inspection			
	<u>NORMAL</u>			
	or			
	<u>ABNORMAL</u>			
Visible Emission From Shaker	Nor			
Visible Emission From Discharge	12 -			
Conveyor System	/Vor			


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Jaime N GORCIG	32-			
Date of Inspection: 8/6/15				
Shift: 1st Shift or 2nd Shift	t Time:	5AM		
Unit	Visual		Comments	ment of the Property and the Control of the Control
	Inspection			
	NORMAL	Carrier and Carrier		
	or			
	<u>ABNORMAL</u>	The second s Second second se		
Visible Emission From Shaker	AloR	<del></del>		
Visible Emission From Discharge	M			
Conveyor System	/1/0R	Parameters of the same of the		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







VISIRI.	FFN	VISSION	NOT	ΙΟΙΤΔΤ	N٩
VISIDE	1	VIIJJIUIV	IVO	AIIO	ı۷~

VISIDEL LIVISSION NOTATIONS				
Inspector: Grosse A Jane	her			
Date of Inspection: 8/7/15				
Shift: 1st Shift or 2nd Shift	Time:	5:00 pm		
Unit Transfer of the Control of the	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Nor	<u>.</u>		
Visible Emission From Discharge	Nac			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Jaime N Gam	rciä			
Date of Inspection: 8/7//5				
Shift: 1st Shift or Znd Shift	Time:	5 Am		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

#### **VISIBLE EMISSION NOTATIONS**

Inspector: Smelko				
Date of Inspection: Aug 8	17			
Shift: 1st Shift or 2nd Shift	t Time:	SAM		
Unit.	Visual Inspection <u>NORMAL</u> or ABNORMAL		Comments	
Visible Emission From Shaker	noR			
Visible Emission From Discharge	gen.			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Conveyor System

# D.1.12 SDS I Daily Visible Emissions Stations Per Each Daylight Shift (Stack SDS 04)



Inspector:	inston				
Date of Inspection: 8/9/15	0				
Shift: 1st Shift or 2nd Shif	t Time:	5 PM			
Cliritic Company of the Company of t	Visual Inspection Normal or ABNORMAL			Comments	
Visible Emission From Shaker	Nov	-cozzo (CO <sup>ORTII)</sup> della 2000 (COORTII) (COORTII) (Cozzo correspondente del describente della correspondente della constituta della correspondente della constituta della correspondente della corresp	Поми в потом в потом работ помера в потом в по		
Visible Emission From Discharge Conveyor System	Nor		Participants and the state of t		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

	<b>EMISS</b>		

A STORE FIGURATIONS			-		
Inspector: Smello					
Date of Inspection: Aug 9	,15				
S ft: 1st Shift or 2nd Shift	t Time:	5,00			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comme	ents	
Visible Emission From Shaker	nor	.0000000000000000000000000000000000000			
Visible Emission From Discharge					

• Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.

NOR

• Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Conveyor System

(Stack SDS 04)

VISIBLE EIVIISSIGIT NO ITTITOTIS				
Inspector: Mr Zenh	org			
Date of Inspection:	13			
Shift: 1st Shift or 2nd Shift	t Time:	5,		
Unit -	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATION
---------------------------

Inspector: Serew	y Hardin			
Date of Inspection:				
Shift: 1st Shift or 2nd Shift	Time:	Soonm		
Unit	Visual		Comments	
	Inspection			
	<u>NORMAL</u>			
	or .			
	<u>ABNORMAL</u>			
Visible Emission From Shaker	somal			
Visible Emission From Discharge				
Conveyor System	Jornal			·

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.







Inspector: Jaine N Gar	Rcia				
Date of Inspection: 8/11/15					
Shift: 1st Shift or 2nd Shift	t Time:	5AM			
Unit	Visual		Comments		
	Inspection			Topico Porto processor Engage (1987) personal	
	<u>NORMAL</u>				
	or				
	<u>ABNORMAL</u>	parameter a particular to			
Visible Emission From Shaker	Nor	granten and the state of the st			
Visible Emission From Discharge	A				
Conveyor System	11/6R				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

Inspector: Ray Mahari	may			
Dete of Inspection: 8/11	115			
Shift: 1st Shift or 2nd Shift	t Time:	3 PM		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	normal	None could state group and the desired land and the state of the state		
Visible Emission From Discharge Conveyor System	normal	*** And the Annual Control of the Annual Con		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS				
Ir pector: Dime N Gall	Cia			
E te of Inspection: $8/12/15$				
Shift: 1st Shift or 2nd Shif	t Time:	5AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Wisible Emission From Shaker	NOR	·		
Wisible Emission From Discharge	NOR			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

	IDLE		ION	MOTA	HOMS	<u> </u>	 		
	ector:	12		A	0	1			_
淵,		1000		<i>Q</i> [	X	white			
ď.		Vecol	100	14	<u>'</u>	WITE -	 	 	
260			1/					 	_

te of Inspection: 8/12/15

ift or 2nd Shift Time: 5:00pm

Unit	Visual Inspection	Comments
	NORMAL	
	or <u>ABNORMAL</u>	
V sible Emission From Shaker	Nor	
Visible Emission From Discharge Conveyor System	Nor	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



#### VISIBLE EMISSION NOTATIONS

Wisible Emission From Shaker

nveyor System

sible Emission From Discharge

N22

In pector:	(	Smelte	>				
Cate of Insp	ection:	Aug 15.	15		-		
Sufft: 1s	t Shift	or 2nd Shift	Time:	5'00			
To Company	Uni	t op skriver store	Visual Inspection		and the second s	omments :	of a second seco
			NORMAL				
1 (ii) 14 (ii) 1 (ii) 15 (ii) 17 (ii)			Or ARNORMAL				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

li .			
//SIBLE	<b>EMISSION</b>	NOTATION	15

Inspector: Garge A	Smetrez			
Date of Inspection: 8/13/1	5	·	1	
Shift: 1st Shift or 2nd S	Shift Time:	8:00 pm		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
sible Emission From Shaker	Nas	_	_	
sible Emission From Discharg	e Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBL	F F	MISS	ION	NOT	ΤΔ	IONS
VIJIDE			-	1101	$\sim$ 1	IUIIJ

Inspector: Jeremy 1	ardn			
Date of Inspection:				
Shift: 1st Shift or 2nd Shift	Time:	Coopm		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOCMAI			
Visible Emission From Discharge Conveyor System	Normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

13.1	CIDI	_	- A A	1001	$\sim$ L I	NIO	$r \wedge r$	IONS
61	SIRI	-	$\vdash I \setminus I$	1 🥆 🥆 1		1/1( )	1 4 1	1( ) \

Inspector: Semm	y Hardin				
Dete of Inspection:	115				
Strift: 1st Shift or 2nd Shift	Time:	Sooan			
Unit	Visual .			Comments	
	Inspection NORMAL		n de formación de la Marco de Marco. Caracter en la característica de la Marco.	The second secon	
	OF TO				
	<u>ABNORMAL</u>				
V sible Emission From Shaker	Norma)				
isible Emission From Discharge					
(onveyor System	mina)				


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS				
Inspector: MTZews	ovra			
Date of Inspection:	-14-15			
Shift: 2st Shift or 2nd Shift	Time:	508		
Unit	Visual		Comments	
kan di karangan dan mengan di permanjuk di Malaysia dan berandakan di Karangan dan berandakan di Karangan dan Karangan dan kangan di Karangan dan di Karangan dan berandakan di Karangan dan berandakan di Karangan dan bera	Inspection			
ne de la company	NORMAL			
	or			
	ABNORMAL			
Visible Emission From Shaker	Darmal			
Visible Emission From Discharge	1			
Conveyor System	Normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS			_	
Smello				
te of Inspection: Aug. 15	>			
ft: 1st Shift or and Shift	Time:	5AM		
Unit .	Visual	Property of the second	Comments	
	Inspection			en e
	<u>NORMAL</u>			
	or and			
	<u>ABNORMAL</u>			
Visible Emission From Shaker	nor	69cctag <sub>0000</sub>		
Visible Emission From Discharge	000-			
Conveyor System	110/2	**************************************		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





<b>VISIBLE</b>	<b>EMISSION</b>	NOTATIONS

Inspector: Mizember	9			
Date of Inspection:	5			
Shift: 1st Shift or 2nd Shift	t Time:	5° 6 m		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Normal.			
Visible Emission From Discharge Conveyor System	Normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS				
Inspector: CAME N COCK	136/06			
Date of Inspection: 0//6/15				
Shift: 1st Shift or 2nd Shift	t Time:	5Am		
Unit Control of the C	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Nor	page 10 to the contract of the		
Visible Emission From Discharge Conveyor System	MBR	And a second		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





Inspector: M. Zewy	~			
Date of Inspection:				
Shift: 1st Shift or 2nd Shift	Time:	50		
and the Unit of a Bell make a	Visual	Professional Control of the Control	Comments	
	Inspection NORMAL			
	or ABNORMAL			
Visible Emission From Shaker	Normal			
Visible Emission From Discharge				
Conveyor System	Normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

<b>V</b> /SIBLE	<b>EMISSI</b>	ON I	NOTATIONS	

Wisible Emission From Discharge

Conveyor System

Inspector: Jaime N Gal	2lra			
Date of Inspection: 8/17/15				
Saift: 1st Shift or 2nd Shif	t Time:	5An		
Unit	Visual Inspection <u>NORMAL</u> or		omments	
Visible Emission From Shaker	ABNORMAL			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS		•			
Inspector:					
Date of Inspection:					
Shift: 1st Shift or 2nd Shif	t Time:				
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Con	mments	
V sible Emission From Shaker	Normal				
Visible Emission From Discharge Conveyor System	Sormal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

١	/ISIBL	F	FΙΛ	122	ION	NO	ΓΔΤ	IONS	
١	/ IOIDL			ເວວ	IUIN	IVO	IAI	כעוטו	ŕ

Inspector: Smello				
Date of Inspection: Aug 19	, 21		-	
Shift: 1st Shift or 2nd Shif	t Time:	5,00		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	nor	-		
Visible Emission From Discharge Conveyor System	nor	YOMASHISI''		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.








Inspector: George A Sons	hez			
Date of Inspection. 8/18/15		·		
Smift: 1st Shift or 2nd Shift	Time:	5:00 pm		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Nor.			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

_/	SIBLE EMISSION NOTATIONS					
11	spector: Smelko					
Ε	te of Inspection:	(1)				
S	ft: 1st Shift or 2nd Shift	Time: ,	TAM			
	Unit participants of the second secon	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Commer	nts in the second secon	
No.	sible Emission From Shaker	noß				
	sible Emission From Discharge onveyor System	nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



VISIBLE EMISSION NOTATION	S				
Inspector: Alex	Bautista				
Date of Inspection:	115				
Shift: 1st Shift or 2hd Sh	nift Time:	3',40m			
Unit	Visual Inspection <u>NORMAL</u>		Comme	ents	
	Or THE				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

V sible Emission From Shaker

Conveyor System

Visible Emission From Discharge

NOR

NOR

VISIBLE EMISSION NOTATIONS			_	
Inspector: Ray	Moharan			
Date of Inspection: 8/20/	15			
Shift: (1st Shift) or 2nd Shift	t Time:	S P.M.		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Noc			
Visible Emission From Discharge Conveyor System	No			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



	EMISS		

Inspector: Jaim N Ga	TLIA				
D te of Inspection: $8/20/15$					
S lift: 1st Shift or Znd Shift	Time:	5 Am			
Unit .	Visual		com	nments	
<ul> <li>Control of the second of the se</li></ul>	Inspection NORMAL		<ul> <li>The state of the s</li></ul>		
	or <u>ABNORMAL</u>			$\begin{array}{cccccccccccccccccccccccccccccccccccc$	
Visible Emission From Shaker	Nor	Project Constitution of Consti			
Visible Emission From Discharge	At				
Conveyor System	110a				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

VISIBLE EMISSION NOTATIONS				
Inspector: Jame N Care	21 Q			
Date of Inspection: 8/21/15				
Shift: 1st Shift or 2nd Shift	: Time:	5AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR	(Second Second S		
Visible Emission From Discharge Conveyor System	NOR	The second secon		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

	01	$\overline{}$	- A	ALCC		NIOT	· ^ ~	IONS
<b>\</b> /	ĸı	-	<b>⊢</b> I\	/// \	11111	$\mathbf{r}$	$\Delta$	11 11/1/5

			<del></del> 1		
Inspector: Alex B	autistu				
Date of Inspection: 8/21	115				
Shift: 1st Shift or 2nd Shift	Time:	Youn			
Unit	Visual			Comments	
	Inspection NORMAL	The state of the s			
	or				
	<u>ABNORMAL</u>		The state of the s	1.00	
V sible Emission From Shaker	NOR	Commencer			
Visible Emission From Discharge		-			
Conveyor System	Nor				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

١,	ACIDI.		$\square \wedge \Lambda$	ISSION	MOTA	TIONS
v	12191	1	FIV!	1ノン1()  /	NULLIA	111111111

Inspector: ) Cline N Cor	alcia			
Date of Inspection: 8/3/19				
Shift: 1st Shift or 2hd Shift	t Time:	5Am		
	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
V sible Emission From Shaker	NOR	(None)		
visible Emission From Discharge onveyor System	Non			


- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



(Stack SDS 04)

Inspector: Smelko				
Date of Inspection: Aug 22,	15			
Shift: 1st Shift or 2nd Shift	Time:	5PM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	nor	indexing and one		
Visible Emission From Discharge Conveyor System	nor	***±35000 type		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



(Stack SDS 04)

Inspector:	everny Harden			
Date of Inspection:	2314			
Shift: 1st Shift or 2nd Shift	Time:	Sagn		
Unit Control of the C	Visual Inspection <u>NORMAL</u> or		Comments	
	<u>ABNORMAL</u>			
Visible Emission From Shaker	Normal			
Visible Emission From Discharge				
Conveyor System	Normal			·

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE EIVIISSION NOTATIONS				
Inspector: Smello				
Date of Inspection: AUG 23,	15			
Shift: 1st Shift or 2nd Shift	Time: 5	60 pm		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	nor			
Visible Emission From Discharge Conveyor System	nor	- Name of the Control		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

SE1		
WCIDII	E ENVICCIONI	<b>NOTATIONS</b>
MAZIDLI	עוכאוכינועום ב	NULAHUNA

Visible Emission From Shaker

Conveyor System


Visible Emission From Discharge

Inspector:	Semals			
Date of Inspection:	5			
Shift: 1st Shift or 2nd S	Shift Time:	6301n		
Unit,	Visual		Comments	
	Inspection NORMAL	The part of the pa		
	or <u>ABNORMAL</u>			

Abnormal

Noem

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



(Stack SDS 04)

Inspector: Smelko				
Date of Inspection: Aug 24	,15			
Shift: (1st Shift) or 2nd Shift	Time:	5AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	nor	,		
Visible Emission From Discharge Conveyor System	hor	<sub>d</sub> eparations.		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

1	CIDI			ISSION	NIOTA	TIONIC
v i	ומוכו	г	T IVI	עונטוכבו	NULLA	11111111

VISIBLE EIMISSION NO ITTIONS				
Inspector: Jaimo N Gaa	Plia			
Date of Inspection: 8/201/5				
Shift: 1st Shift or 25d Shift	t Time:	5Am		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		omments	
Visible Emission From Shaker	Nor	Consequence of the Consequence o		
Visible Emission From Discharge Conveyor System	Non	y contract our account of the contract of the		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBL				

Visible Emission From Discharge

Çonveyor System

Inspector: George A	onche =			
Date of Inspection. 8/20/18				
Shift: st Shift or 2nd Shift	Time:	S-Odpen		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	1			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE EIMISSICITION TO TATIONS				
Inspector: Jeremy Har	dih			•
Date of Inspection: 8/76/	<u> </u>			
Shift: 1st Shift or 2nd Shif	Time: 57	ge an		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	revery			
Visible Emission From Discharge Conveyor System	semil			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.





#### **VISIBLE EMISSION NOTATIONS**

In pector: Jaime N G	ORCIA				
is e of Inspection: $8/26//5$					
it: 1st Shift or 2nd Shift	Time:	5AM			
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		-Comr	nents	
sible Emission From Shaker	Nor	- Niji procedori kanada ka			
Visible Emission From Discharge Conveyor System	Non	* Control of the Cont			


(Stack SDS 04)

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

evised 5/1/2015

VISIBLE EMISSION NOTATIONS				
Inspector: Smelto				
Date of Inspection: 8-27				
Shift: 1st Shift or 2nd Shift	Time:	TAM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	And the second s
Visible Emission From Shaker	NOR	900000000000000000000000000000000000000		
sible Emission From Discharge	nor	Altazone i P		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



1000
70 m

V	115	IBI	F	F٨	<b>AISS</b> I	ION	NOT	ΤΔΤ	101	NS
ν	4.0	יטיי	_∟	L11	11133	$\mathbf{v}$	11001	$\sim$ 1	101	N.J

Inspector: Jeverny Hardin	7			
Date of Inspection: 8/27/05				
Shift: 1st Shift or 2nd Shift	t Time:	Spm.		
	Visual Inspection <u>NORMAL</u> or ABNORMAL		omments	
Visible Emission From Shaker	Normal			
Visible Emission From Discharge Conveyor System	Normay			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Revised 5/1/2015

١	/1	СI	D I	E	$E^{\Lambda}$	Λ	ICC	ION	NO	ГΛТ		ıc
١	/ I.	וכ	Ы		Εľ	VΙ	122	IUN	INO	IAI	יוטו	1.7

7000			
Inspector: Coull Land			
Date of Inspection: 45-30-	15		
Shift: 1st Shift or 2nd Shift	Time:	5:00 Am	
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		
Visible Emission From Shaker	V0V		
Visible Emission From Discharge Conveyor System	701		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBL			

Visible Emission From Discharge

Conveyor System

nor

Inspector: Smello				
Dete of Inspection: Aug. 24	1>			
Shift: 1st Shift or 2nd Shift	Time:	5pm		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	BOR	School and the second		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

(Stack SDS 04)

VISIBLE FIVISSION NOTATIONS					
Inspector: ) and Land					
Date of Inspection:					
Shift: 1st Shift or 2nd Shift	: Time:	5'00 M			
Unit Problems	Visual		# <b>∠Com</b> m	ents 📜 📜 🖫	
	Inspection		and the second of the second o	The second of th	en de la companya del companya de la companya del companya de la c
	<u>NORMAL</u>	$\mathbb{Z} = \{ \{1, 1, 2, 3, 3, 4, 2, 3, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4, 4,$		$\{V_{i},v_{i},v_{i}\}\in\{v_{i+1},v_{i}\}, \forall i\in \mathbb{N}\}$	
	or		District and the second		
	<u>ABNORMAL</u>				
Visible Emission From Shaker	0 70				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Visible Emission From Discharge

Conveyor System


VISIBLE EMISSION NOTATIONS				
Inspector: Smelko				
Dite of Inspection: & Aug 2	d D			
Shift: 1st Shift or 2nd Shift	t Time:	5PM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		ments	
Visible Emission From Shaker	nob	1988000400000.		
Visible Emission From Discharge		1000appower"		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

Conveyor System

IBLE EMISSION NOTATIONS				
pector:				
e of Inspection:		-		
SF ift: 1st Shift or 2nd Shi	ft Time:			
	Visual Inspection <u>NORMAL</u> or ABNORMAL	Con	nments	
V sible Emission From Shaker	Nov			
Visible Emission From Discharge Conveyor System	Nor			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.



21					
√\SIBL	F	<b>FMI</b>	SSION	NOTA	TIONS

Inspector:			]	
M. PHI	harm PS			
Date of Inspection:				
Shift: 1st Shift or 2nd Shift	Time:	5 AM		
Unit	Visual		Comments.	
programme and the second s	Inspection		and the second s	Programme Commission (1994)
	<u>NORMAL</u>			
	or			$ \frac{1}{2} \lim_{t \to \infty} \frac{1}{2} \lim$
	<u>ABNORMAL</u>		And the second s	and the second s
sible Emission From Shaker	10.0			
	NORMAL	and the second s		
sible Emission From Discharge		_		
onveyor System	AXRMAL	Security		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions.
- Opacity is a measure of the defree to which emissions reduce the transmission of light and obscure the view of an object in the background.

levised 5/1/2015